



**RD TECHNOLOGY**

---

860 Isis Ct, Reno, NV 89512 775 843-5952, email - [bobmiller@gbis.com](mailto:bobmiller@gbis.com)

## **HAMLINK BULLETIN 001**

November 19, 2011

The length of the coax assembly between the DCI filter 146H and the IC2200 radio must be as close to 18, 54, or 89 inches as possible, avoid 42 and 84 inches.

We found in one installation, the packet transmissions were more of a squawk than a perfect packet (chirp). The length of the coax the we used was 42 inches and caused the problem, so keep the length as recommended above.

Bob Miller  
RD Technology  
[bobmiller@gbis.com](mailto:bobmiller@gbis.com)  
775 843-5952